

FRAISES 1/4 DE CERCLE
 VIERTELKREISFRÄSER
 QUARTER CIRCLE CUTTERS

Z = 2



ISO 513: **PMKSN**

D ₁	L ₁	L ₂	D _{h6}	L	R	HM
0.50	0.12	8	3	38	0.10	■
0.50	0.18	7	3	38	0.15	■
0.50	0.24	7	3	38	0.20	■
0.50	0.30	7	3	38	0.25	■
0.50	0.36	6	3	38	0.30	■
0.50	0.48	6	3	38	0.40	■
0.50	0.60	6	3	38	0.50	■
0.50	0.70	5	3	38	0.60	■
0.50	0.80	4	3	38	0.70	■
0.80	0.90	3	3	38	0.80	■
0.80	1.00	3	3	38	0.90	■
0.80	1.10	3	3	38	1.00	■

